Air Quality Group HAZARD CONTROL PLAN AND WORK AUTHORIZATION Page 1 of _____ This form is from ESH-17-035

1. Describe the work to be performed (use continuation page if needed) or give procedure number,							
revision number, and title. HCP-ESH-17-Computers, R2 Title: Installation, Repair, and Maintenance of Computers							
This Hazard Control Plan (HCP) covers activities associated with installation, maintenance, and repair							
of computers and related peripheral equipment by ESH-17 group members. This plan also covers							
installation of UPS systems and external battery connection/replacement.							
2. Describe potential hazards associated with the work (use continuation page if needed).							
a. Lifting/Moving Hazards							
b. Electrical Hazards							
c. Cut, Puncture and Pinch Hazards							
d. Burn Hazards							
3. For each hazard, list the likelihood and severity, and the resulting initial risk level (before any work							
controls are applied, as determined according to LIR300-00-01.0, section 7.2)							
a. Lifting/Moving Hazards: occasional / critical = medium							
b. Electrical Hazards: improbable / moderate = minimal							
c. Cut, Puncture and Pinch Hazards: occasional / negligible = minimal							
d. Burn Hazards: occasional / negligible = minimal							
Overall initial risk: Minimal Low Medium High							
4. Applicable Laboratory, facility, or activity operational requirements directly related to the work:							
None List: Work Permits required? No List:							
5. Describe how the hazards listed above will be mitigated (e.g., safety equipment, administrative							
controls, etc.):							
NOTE: No worker in ESH-17 is authorized to perform internal maintenance or repair on UPS systems							
or battery packs.							
a. Lifting/Moving Hazards: workers shall use proper lifting techniques and equipment (e.g., support							
belt, carts, etc.) for moving and installing equipment. The worker shall seek help for items which are							
too heavy. Equipment shall be installed on suitable platforms.							
Authorized worker should oversee the proper lifting techniques of helpers.							
see continuation page							

	Air Quality Group	HCP-ESH-17-Computers, R2					
HAZARD CONTROL PI	LAN AND WORK	AUTHORIZATION Page 2 of This form is from ESH-17-038					
6. Knowledge, skills, abilities, and trai	ning necessary to safe	ely perform this work (check one or both):					
	per ESH-17-032) and	training to applicable procedure.					
Other → Describe: Authorized personnel must:							
watch a videotape on proper lifting	0 0 1						
complete the training plan "R&D E	lectrical Workers: Non	-Energized or Electronic/Computer					
Technicians: Non-Energized." Recommended:							
exercises, as recommended by Welli	ness Center trainers, to	strengthen and tone muscles used in					
lifting.	<u> </u>						
7. Any wastes and/or residual materials? (check one) None List: Note: the batteries used in UPS systems are recyclable and shall not be disposed of in the trash.							
Batteries shall be returned to a factory-authorized service center.							
8. Considering the administrative and engineering controls to be used, the <i>residual</i> risk level (as determined according to LIR300-00-01.0, section 7.3.3) is (check one):							
Minimal							
9. Emergency actions to take in event	t of control failures or a	bnormal operation (check one):					
None List:							
		opportunities for improvements in safety					
and report these to the safety officer o	r group leader.						
Preparer(s) signature(s) [NOTE: Training to a procedure constitutes aut							
reviewed the safety of this proposed work with performing this work.	the group safety officer and	d I commit to follow safe practices when					
_							
Employee signature	Name (print)	Date					
Additional employee signature (optional)	Name (print)	Date					

Group leader or safety officer review.

Additional employee signature (optional)

I have reviewed the proposed work with 1) the preparer(s) and 2) employees who will perform the work (if not described in a procedure) and I believe the hazards and safety concerns have been adequately addressed. The work as described above is hereby authorized. This authorization expires one year after the date below.

Date

Group leader or safety officer signature Name (print) Date

Name (print)

HAZARD CONTROL PLAN AND WORK AUTHORIZATION

Page 3 of

This form is from ESH-17-035

Hazard Control Plan continuation page. Give item number being continued. 5. cont.)

1	T 1	. •	1 T T	r	1
h.	HID	etrica	al H	272	rde.

- -- Computer and peripherals: ESH-17 personnel are not authorized to perform work on any internal power supply and shall not open the interal power supply protective case. Since the power supply will not be opened, work performed on computer systems by ESH-17 workers is not considered hazardous in accordance with LIG 402-600-01, Table 2.1
- -- UPS: ESH-17 workers are not authorized to perform internal maintenance or repair on UPS systems or battery packs. ESH-17 workers may set up UPS systems and connect/replace external batteries. The UPS must be disconnected from power sources and loads and deenergized before battery connection/replacement. To deenergize the UPS and connect/replace the battery(s), read and follow the manuafacturer's instructions.
- c. Cut, Puncture, Pinch Hazards: Before beginning work, workers shall visually identify any sharp edges, tight spaces or hinged parts which might cause injury.
- d. Burn Hazards: Before beginning work, workers shall identify any potentially hot (thermally) parts inside the equipment (mainly printers).